

Re: error SRC 11007631 Power/Cooling

Source: <http://unix.derkeiler.com/Mailing-Lists/AIX-L/2007-02/msg00016.html>

- *From:* Rick Saylor <rsaylor@xxxxxxxxxxxxx>
 - *Date:* Fri, 2 Feb 2007 09:23:19 -0600
-

Dave,

I seen this error before on one of my machines. It was caused be a loose power cord. You might want to ensure that all power cords are seated properly. Also, consider reporting this to IBM hardware support because it could be a failing power supply or fan.

Thanks,
Rick Saylor
Austin Community College

At 07:46 AM 2/2/2007, you wrote:

Hope this isn't a FAQ....

I keep getting the following error:

LABEL: SCAN_ERROR_CHRP
IDENTIFIER: BFE4C025

Description
UNDETERMINED ERROR

Failure Causes
UNDETERMINED

Resource tested: sysplanar0
Resource Description: System Planar
Location:
SRC: 11007631
Description: Power/Cooling subsystem Unrecovered Error, bypassed with loss of redundancy. Refer to the system service documentation for more information.

I thought I remember reading that this was a "bug"....

Info:

Re: error SRC 11007631 Power/Cooling

System Model: IBM,9131-52A
Machine Serial Number: 100D6CG
Processor Type: PowerPC_POWER5
Number Of Processors: 4
Processor Clock Speed: 1499 MHz
CPU Type: 64-bit
Kernel Type: 64-bit
LPAR Info: 1 10-0D6CG
Memory Size: 3920 MB
Good Memory Size: 3920 MB
Platform Firmware level: SF240_219
Firmware Version: IBM,SF240_219
OS 5300-05

Any help?

Thanks!

Dave Zarnoch
davezarn@xxxxxxxxxxxx

Get live scores and news about your team: Add the Live.com Football Page
<http://www.live.com/?addtemplate=football>