

## Ultra10 OPB flash update

**Source:** <http://unix.derkeiler.com/Newsgroups/comp.sys.sun.hardware/2004-01/0131.html>

---

**From:** Gary P. Fiber ([g.fiber\\_at\\_verizon.net](mailto:g.fiber_at_verizon.net))

**Date:** 01/11/04

Date: Sun, 11 Jan 2004 20:04:11 GMT

I am having a problem getting my Ultra 10 to preform the flash update. I am running SuSE linux 7.3 for sparc64. I have moved the flash enable jumper to pins 2 & 3. Copied the flash-update-Ultra510-latest file to the / partition of the hard disk. I type boot disk /flash-update-Ultra510-latest at the OK prompt. I get the boot disk information then SILO: on another line I get file error: Multiple loadable segments in your elf image. and it stops there. I tried doing a boot cdrom which has the files on it and I get a bad disk number. The cdrom will boot a SuSE linux cdrom just fine. Any ideas?

Gary Fiber