

Re: Re[4]: reproducible watchdog timeout in bge

Source: <http://unix.derkeiler.com/Mailing-Lists/FreeBSD/net/2007-01/msg00217.html>

- *From:* MQ <antinvidia@xxxxxxxx>
 - *Date:* Wed, 31 Jan 2007 22:27:54 +0800
-

2007/1/28, MQ <antinvidia@xxxxxxxx>:

2007/1/27, Wishmaster <wishmaster@xxxxxxxx>:

>
> Hello MQ,
>
> Saturday, January 27, 2007, 5:31:49 PM, you wrote:
>
> M> I have two boxes with onboard bge, one using 5780, the other
> M> 5701. Neither of them has your problem. I think there may be some
> M> problems with your software or hardware configuration.
>
>
> I don't think so. I have two different motherboards and two
> different freebsd distributions on them (6.1/amd64 and 6.2/i386). On
> both motherboards there
> are bcm5721 onboard network chips and both configurations have the
> same issue.
>
> Can you tell me do you have smp kernel?
>
> p.s. On both machines I have clear installation of freebsd. i.e.
> there is nothing except SMP in my kernel.
> --
> Best regards,
> Wishmaster mailto: wishmaster@xxxxxxxx
>
>
> _____
> freebsd-net@xxxxxxxx mailing list
> <http://lists.freebsd.org/mailman/listinfo/freebsd-net>
> To unsubscribe, send any mail to "freebsd-net-unsubscribe@xxxxxxxx"
>

One of my boxes is dual Opteron 250 with dual 5780 onboard, SMP kernel.

Re: Re[4]: reproducible watchdog timeout in bge

The other is HP NC6000 with 5701, GENERIC kernel. Perhaps 5721 has some big differences from other chips.

Today, I got a mainboard manufactured by Tyan with onboard 5721. I got into a situation even stranger than yours, the NIC was identified as 5750, and printed RX CPU self-diagnostics failed! It's so strange, I'll go deeper into this problem when I get time.

freebsd-net@xxxxxxxxxxx mailing list

<http://lists.freebsd.org/mailman/listinfo/freebsd-net>

To unsubscribe, send any mail to "freebsd-net-unsubscribe@xxxxxxxxxxx"