

Re: ICH9 ethernet part (82566) woes

Source: <http://unix.derkeiler.com/Mailing-Lists/FreeBSD/stable/2007-09/msg00127.html>

- *From:* "Jack Vogel" <jfvogel@xxxxxxxxxx>
 - *Date:* Mon, 24 Sep 2007 10:07:26 -0700
-

On 9/23/07, Daniel O'Connor <doconnor@xxxxxxxxxxxxxx> wrote:

On Fri, 21 Sep 2007, Jack Vogel wrote:

Then on the side menu pick network connectivity, then server adapter, and select an adapter, it shouldnt matter which. Once at that page there is a pulldown for OS, select FreeBSD and tada...

I found this ->

<http://support.intel.com/support/network/sb/CS-006120.htm>

Which leads me to v6.4.1 which claims support for the part in question (checking the source shows the PCI ID)

It also has patches for TSO, although it appears to be optional.

I just installed it and it appears to work fine, I haven't done any performance testing though, however I am only interested in basic connectivity.

I just looked however and the latest on there is from the last release, 6.5.6 which is only for 7. E1000 was not the real focus of this release, the new Oplin 10G was, however as I said, 6.6.6 has the nice feature of compiling on both OS versions, and it has the support you need.

Just give them a week and I think it will be there, maybe I can take a break from my other work and get to the MFC.

As the 6.4.1 driver works I am happy :)

Yes, that's just one release earlier than the one I suggested, but if you're happy, hey, who am I to complain :)

Jack

Re: ICH9 ethernet part (82566) woes

freebsd-stable@xxxxxxxxxxx mailing list

<http://lists.freebsd.org/mailman/listinfo/freebsd-stable>

To unsubscribe, send any mail to "freebsd-stable-unsubscribe@xxxxxxxxxxx"