

a1000 problem

Source: <http://unix.derkeiler.com/Mailing-Lists/SunManagers/2003-08/0390.html>

From: Franky Van Liedekerke (*liedekef_at_pandora.be*)

Date: 08/21/03

Date: Thu, 21 Aug 2003 15:14:15 +0200

To: sunmanagers@sunmanagers.org

Hi,

I'm trying to get my E250 solaris 8 machine to talk to an old a1000 which was lying around here. After installing the latest recommended patches, the 6.221 raid manager and some small patches (112126-06) and , I rebooted the machine and it recognized the A1000. Whoohoo! But then it happened: the firmware needed to be upgraded, so I started the fwutil command, but because I'm a bit blnd I did
fwutil 02050632.apd c1t5d0
instead of
fwutil 02050632.bwd c1t5d0

The command frooze on me and there was nothing else I could do but reboot the machine and A1000 because the tools (like raidutil) no longer were able to talk to the A1000.

But now the A1000 is no longer recognized by the machine:

```
# ./nvutil -v
There are no devices (controllers) in the system; nvutil terminated.
# ./hot_add
drvconfig: driver failed to attach: ssd
WARNING: set_drivers: No arrays were found that are controlled by either
the sd or the ssd driver
```

So you see I could use a little help here ...

Did I screw up my firmware controller? Do I need to install patch 106503-08? I was reluctant to do this one because it's a flash upgrade of the system, but maybe it needs this?

any help is appreciated ...

Franky

sunmanagers mailing list
sunmanagers@sunmanagers.org
<http://www.sunmanagers.org/mailman/listinfo/sunmanagers>