

comp.unix.aix: Mysterious error after install a mksysb on a SP node ... urgent !!!

Mysterious error after install a mksysb on a SP node ... urgent !!!

Source: <http://unix.derkeiler.com/Newsgroups/comp.unix.aix/2003-04/0239.html>

From: Friedhelm Neyer (Friedhelm.Neyer@t-online.de)

Date: 04/07/03

From: Friedhelm Neyer <Friedhelm.Neyer@t-online.de>

Date: Mon, 07 Apr 2003 19:45:37 +0200

Hi all

I've create a mksysb from a running SP node (AIX 4.3.3 ML11) and try to install this image on an other (new) node in the same cluster. On this node there was a AIX 4.3.3 ML10 installed and the machine has running fine all the time...

First I set the node to install (spbootins ...) then do a nodecond

<frame><slot>

The NIM installation was set to noprompt and complete overwrite.

The first result was an error which says not enough to generate filesystems and/or logical volumes.

OK, without any idea why this happens I boot the node in diag mode and format the two internal hd's (hdisk0 and hdisk1 – each 36 GB) and again a nodecond like before. Now the installation process can create all the lv's and fs's and ended without any error. Now the node begins to reboot until I saw in a s1term window the RS/6000 logo – thats it – then tehre appears an error which says: --- unrecognized client program format --- and an error code of 20EE000B on the console – the LED shows me a code of 4BA00830 (?). A search for the 20EE000B says, that the deblocker cannot be load and the reason should a to low microcode for AIX 4.3.3 – but this is impossible, because the node was running for long time with AIX 4.3.3 the last months with ML10.

Anyx hints or tips to point me in the right direction ??

Friedhelm

Please send any answers also to

Friedhelm.Neyer@t-systems.com

it's really urgent ...

Thx

Mysterious error after install a mksysb on a SP node ... urgent !!!