

Re: error SRC 11007631 Power/Cooling

Source: <http://unix.derkeiler.com/Mailing-Lists/AIX-L/2007-02/msg00018.html>

- *From:* David Zarnoch <davezarn@xxxxxxxxxxxx>
 - *Date:* Fri, 2 Feb 2007 20:40:38 +0000
-

Thanks!!!

Dave Zarnoch
davezarn@xxxxxxxxxxxx

From: Rick Saylor <rsaylor@xxxxxxxxxxxx>
Reply-To: IBM AIX Discussion List <aix-l@xxxxxxxxxxxx>
To: aix-l@xxxxxxxxxxxx
Subject: Re: error SRC 11007631 Power/Cooling
Date: Fri, 2 Feb 2007 09:23:19 -0600
MIME-Version: 1.0
Received: from Princeton.EDU ([128.112.131.112]) by bay0-mc7-f2.bay0.hotmail.com with Microsoft SMTPSVC(6.0.3790.2444); Fri, 2 Feb 2007 07:24:50 -0800
Received: from smtpserver2.Princeton.EDU (smtpserver2.Princeton.EDU [128.112.129.148]) by Princeton.EDU (8.13.8/8.13.8) with ESMTP id I12FO85T005259; Fri, 2 Feb 2007 10:24:08 -0500 (EST)
Received: from lists.Princeton.EDU (listsv440.Princeton.EDU [128.112.131.10]) by smtpserver2.Princeton.EDU (8.12.9/8.12.9) with ESMTP id I127XaZG028506; Fri, 2 Feb 2007 10:24:03 -0500 (EST)
Received: by LISTS.PRINCETON.EDU (LISTSERV-TCP/IP release 15.0) with spool id 14714189 for aix-l@xxxxxxxxxxxx; Fri, 2 Feb 2007 10:23:29 -0500
Received: from Princeton.EDU (postoffice04.Princeton.EDU [128.112.131.112]) by lists.Princeton.EDU (8.13.1/8.13.1) with ESMTP id I12FNRNK013832 for <aix-l@xxxxxxxxxxxx>; Fri, 2 Feb 2007 10:23:27 -0500 (EST)
Received: from Princeton.EDU (postoffice04.Princeton.EDU [128.112.131.112]) by Princeton.EDU (8.13.8/8.13.8) with ESMTP id I12FNRue004812 for <aix-l@xxxxxxxxxxxx>; Fri, 2 Feb 2007 10:23:27 -0500 (EST)
Received: from emfw3.Princeton.EDU (emfw3.Princeton.EDU [128.112.129.100]) by Princeton.EDU (8.13.8/8.13.8) with ESMTP id I12FNQhc004798 for <aix-l@xxxxxxxxxxxx>; Fri, 2 Feb 2007 10:23:26 -0500 (EST)
Received: from mailbox.austincc.edu (monk.austincc.edu [198.213.3.10]) by emfw3.Princeton.EDU (Spam Firewall) with ESMTP id DB3A1189E94 for

Re: error SRC 11007631 Power/Cooling

<aix-l@xxxxxxxxxxxxxx>; Fri, 2 Feb 2007 10:23:25 -0500 (EST)
Received: from rsaylor3.austincc.edu (m20677151072.austincc.edu [206.77.151.72]) by
mailbox.austincc.edu (8.12.3/8.12.3/Debian-7.2) with ESMTP id I12FNOJr013774 for
<aix-l@xxxxxxxxxxxxxx>; Fri, 2 Feb 2007 09:23:25 -0600
X-Message-Info: LsUYwwHHNt0W9sCp6iUVQuo72BOOKkxh3RVeyAejq14=
X-ASG-Debug-ID: 1170429805-1b4800ef0000-b5t46D
X-Barracuda-URL: <http://128.112.129.100:8000/cgi-bin/mark.cgi>
X-Barracuda-Connect: monk.austincc.edu[198.213.3.10]
X-Barracuda-Start-Time: 1170429805
X-Mailer: QUALCOMM Windows Eudora Version 7.0.1.0
X-ASG-Orig-Subj: Re: error SRC 11007631 Power/Cooling
References: <BAY103-F1711A4034ACAECFE166217DE9B0@xxxxxxxx>
X-Barracuda-Virus-Scanned: by Barracuda Spam Firewall at Princeton.EDU
X-Proofpoint-Spam-Details: rule=quarantine_notspam policy=quarantine score=0 mlx=0
adultscore=0 adjust=0 reason=mlx engine=3.0.0-0701160000 definitions=main-0702020017
X-Spam-KB: <http://www.Princeton.EDU/spam>
Newsgroups: bit.listserv.aix-l
X-To: IBM AIX Discussion List <aix-l@xxxxxxxxxxxxxx>
Precedence: list
List-Help: <<https://lists.princeton.edu/cgi-bin/wa?LIST=aix-l>>,
<<mailto:LISTSERV@xxxxxxxxxxxxxx?body=INFO%20aix-l>>
List-Unsubscribe: <<mailto:aix-l-unsubscribe-request@xxxxxxxxxxxxxx>>
List-Subscribe: <<mailto:aix-l-subscribe-request@xxxxxxxxxxxxxx>>
List-Owner: <<mailto:aix-l-request@xxxxxxxxxxxxxx>>
List-Archive: <<https://lists.princeton.edu/cgi-bin/wa?LIST=aix-l>>
Return-Path: owner-aix-l@xxxxxxxxxxxxxx
X-OriginalArrivalTime: 02 Feb 2007 15:24:50.0971 (UTC)
FILETIME=[481A36B0:01C746DE]

Dave,

I seen this error before on one of my machines. It was caused be a loose power cord. You might want to ensure that all power cords are seated properly. Also, consider reporting this to IBM hardware support because it could be a failing power supply or fan.

Thanks,
Rick Saylor
Austin Community College

At 07:46 AM 2/2/2007, you wrote:

Hope this isn't a FAQ....

I keep getting the following error:

LABEL: SCAN_ERROR_CHRP
IDENTIFIER: BFE4C025

Description
UNDETERMINED ERROR

Re: error SRC 11007631 Power/Cooling

Failure Causes
UNDETERMINED

Resource tested: sysplanar0
Resource Description: System Planar
Location:
SRC: 11007631
Description: Power/Cooling subsystem Unrecovered Error, bypassed with loss of redundancy. Refer to the system service documentation for more information.

I thought I remember reading that this was a "bug"....

Info:

System Model: IBM,9131-52A
Machine Serial Number: 100D6CG
Processor Type: PowerPC_POWER5
Number Of Processors: 4
Processor Clock Speed: 1499 MHz
CPU Type: 64-bit
Kernel Type: 64-bit
LPAR Info: 1 10-0D6CG
Memory Size: 3920 MB
Good Memory Size: 3920 MB
Platform Firmware level: SF240_219
Firmware Version: IBM,SF240_219
OS 5300-05

Any help?

Thanks!

Dave Zarnoch
davezarn@xxxxxxxxxxxx

Get live scores and news about your team: Add the Live.com Football Page
<http://www.live.com/?addtemplate=football>

FREE online classifieds from Windows Live Expo ? buy and sell with people you know
http://clk.atdmt.com/MSN/go/msnkwex0010000001msn/direct/01/?href=http://expo.live.com?s_cid=Hotmail_tagline

Re: error SRC 11007631 Power/Cooling