

RE: Intel 6300ESB SATA and TIMEOUT – WRITE_DMA

Source: <http://unix.derkeiler.com/Mailing-Lists/FreeBSD/hackers/2006-03/msg00230.html>

- *From:* Alain Hebert <ahebert@xxxxxxxxxxx>
 - *Date:* Thu, 23 Mar 2006 14:55:52 -0500
-

Hi,

I'm about to invest in some Tyan Transport GT20 B5350G20S2H-LC.

But since my epic battle trying to make the Promise Fasttrak 2300TX (PDC20580?) works right in Raid1, 2 weeks ago I'm a bit concern about those new SATA controllers.

Myself I have a PDC20378 in (heavy) production with 5.4-CURRENT and its flawless, I also have a 3ware also in heavy production (way cool but pricy).

But I'm wondering if the 6300ESB controller was still stable in 6-CURRENT?

And for Roger,

> Oh well, replacing the SATA cable fixed it, I'm terribly sorry about that :(

Meaning? I know of only 1 cable format. Thanks.

Anybody need a Promise Fasttrak 2300TX to develop/test/fix?

I know that the 6-CURRENT driver wasn't recognizing the Raid config with the 2.5.x firmware, but was ok with the original firmware (2.0.x)

Let me know.

Alain Hebert ahebert@xxxxxxxxxxx PubNIX Inc. P.O. Box 175 Beaconsfield, Quebec H9W 5T7
tel 514-990-5911 <http://www.pubnix.net> fax 514-990-9443

freebsd-hackers@xxxxxxxxxxx mailing list

<http://lists.freebsd.org/mailman/listinfo/freebsd-hackers>

To unsubscribe, send any mail to "freebsd-hackers-unsubscribe@xxxxxxxxxxx"