

Re: FreeBSD on IBM x345 2U server?

Source: <http://unix.derkeiler.com/Mailing-Lists/FreeBSD/isp/2003-05/0064.html>

From: Antonio Torres (antonio.torres_at_newspace.net.br)

Date: 05/21/03

Date: Wed, 21 May 2003 07:52:54 -0300

To: freebsd-isp@freebsd.org

On Wed, 21 May 2003 11:11:35 +0200

Christoffer Pio <cp@cvt.dk> wrote:

> *Actually, I tried install FreeBSD 4.8 at first, it did not*
> *detect the controller. Then I tried 5.0 and checked out*
> *the drivers.flp option as well. No luck either .. I'm installing*
> *from floppies (kern.flp and mfsroot.flp), I cannot imagine*
> *how it could make a difference installing from a CDROM.*
>
> *Christoffer*

Please, read the docs from FreeBSD 5.0

The difERENCE comes from a new "CD boot layout", is not "floppy size limited" ...

[]s

--

Antonio Torres
antonio.torres@newspace.net.br

freebsd-isp@freebsd.org mailing list

<http://lists.freebsd.org/mailman/listinfo/freebsd-isp>

To unsubscribe, send any mail to "freebsd-isp-unsubscribe@freebsd.org"