

Re: Re[4]: reproducible watchdog timeout in bge

Source: <http://unix.derkeiler.com/Mailing-Lists/FreeBSD/net/2007-01/msg00196.html>

- *From:* MQ <antinvidia@xxxxxxxx>
 - *Date:* Sun, 28 Jan 2007 02:23:52 +0000
-

2007/1/27, Wishmaster <wishmaster@xxxxxxxx>:

Hello MQ,

Saturday, January 27, 2007, 5:31:49 PM, you wrote:

M> I have two boxes with onboard bge, one using 5780, the other
M> 5701. Neither of them has your problem. I think there may be some
M> problems with your software or hardware configuration.

I don't think so. I have two different motherboards and two
different freebsd distributions on them (6.1/amd64 and 6.2/i386). On both
motherboards there
are bcm5721 onboard network chips and both configurations have the
same issue.

Can you tell me do you have smp kernel?

p.s. On both machines I have clear installation of freebsd. i.e.
there is nothing except SMP in my kernel.

--

Best regards,

Wishmaster <mailto:wishmaster@xxxxxxxx>

freebsd-net@xxxxxxxxxxxxx mailing list

<http://lists.freebsd.org/mailman/listinfo/freebsd-net>

To unsubscribe, send any mail to "freebsd-net-unsubscribe@xxxxxxxxxxxxx"

One of my boxes is dual Opteron 250 with dual 5780 onboard, SMP kernel. The
other is HP NC6000 with 5701, GENERIC kernel. Perhaps 5721 has some big
differences from other chips.

Re: Re[4]: reproducible watchdog timeout in bge

freebsd-net@xxxxxxxxxxx mailing list

<http://lists.freebsd.org/mailman/listinfo/freebsd-net>

To unsubscribe, send any mail to "freebsd-net-unsubscribe@xxxxxxxxxxx"