

## Re: Various problems with re(4) on a PCIe 8168/8111B onboard NIC

---

*Source:* <http://unix.derkeiler.com/Mailing-Lists/FreeBSD/stable/2007-07/msg00532.html>

---

- *From:* Michael Nottebrock <[lofi@xxxxxxxxxxx](mailto:lofi@xxxxxxxxxxx)>
  - *Date:* Tue, 31 Jul 2007 01:31:59 +0200
- 

On Monday, 30. July 2007, Pyun YongHyeon wrote:

Thanks for reporting. I don't have these hardware models so I couldn't verify the issue. After reading the vendor's code I've made attached patch. I don't know whether it works or not, it's just guess work.

Works fine here!

Cheers,

—

,\_, | Michael Nottebrock | [lofi@xxxxxxxxxxx](mailto:lofi@xxxxxxxxxxx)  
(/^ ^\)| FreeBSD – The Power to Serve | <http://www.freebsd.org>  
\u/ | K Desktop Environment on FreeBSD | <http://freebsd.kde.org>

***Attachment: [signature.asc](#)***

*Description:* This is a digitally signed message part.