

[HPADM] which driver in kernel for C9572 robotics

Source: <http://unix.derkeiler.com/Mailing-Lists/HP-UX-Admin/2003-04/0100.html>

From: Derko Drukker (*Derko.Drukker_at_rivm.nl*)

Date: 04/25/03

To: hpux-admin@dutchworks.nl

Date: Fri, 25 Apr 2003 14:05:26 +0200

Dear Listeners,

Which driver should be loaded into the kernel of an rp2405 HPUX 11i system to be able to use the robotics of the C9572 Ultrium 1/8 autoloader ?

Derko

Derko Drukker

Rijksinstituut voor Volksgezondheid en Milieu (RIVM) – National Institute of Public Health and the Environment

Laboratorium voor Milieumetingen (LVM) – Laboratory of Environmental Monitoring

Postbus 1

3720 BA Bilthoven – The Netherlands

tel. 030 2743418

fax 030 2287531

--

---> Please post QUESTIONS and SUMMARIES only!! <---

To subscribe/unsubscribe to this list, contact majordomo@dutchworks.nl
Name: hpux-admin@dutchworks.nl Owner: owner-hpux-admin@dutchworks.nl

Archives: ftp.dutchworks.nl:/pub/digests/hpux-admin (FTP, browse only)
 <http://www.dutchworks.nl/htbin/hpsysadmin> (Web, browse & search)